



	A
1.07074.50	72
1.07074.52	72
1.07074.60	92
1.07074.62	92




1.43025.65




43190
E = 65 - 95

1




1.43000.65, 1.43110.65, 1.43114.65

4




1.43091.00.0

7




43191
E = 65 - 95

2




1.43020.65, 1.43024.65, 1.43120.65, 1.43130.65,

5



1.43115.65

8





43520, 43530, 43620, 43630, 43631, 43632

E = 25 - 30 - 35 - 40 - 45



3

6


9



13



14



15